Transpoundary Spill NPDES CAULUS928 Order No. R9-2014-0009, Amended by R9-2014-0094					
TypeAx B (CAL OES 1-800-852-7550)					
Name of Person Reporting Spill Steven Smullen					
Telephone No. of Person Reporting 619-662-7601					
Spill Location/NameTijuana River at the International Boundary					
GPS Coordinates _32.32.30 N, 117.2.18 W					
Spill Reached:Drainage ChannelDrainage StructurexSurface Water					
Spill Reached:MS4 MS4 Owner					
Vol Spill to MS4Vol Recovered from MS4					
Estimate Spill Volume from All Sources0.223 million gallons (MG)					
Volume That Reached: Surface Water, Drainage Channel, Not Recovered from MS40.223 MG					
Total Recovered Volume0_					
Number of Spill Appearance Points1					
Appearance DescriptionsSlightly cloudy water					
Spill Flow: Start Date 12/11/17Start Time0245					
Notification: Date12/11/17 Time1000					
Operator Arrival: Date12/11/17 Time0430					
Spill Flow: End Date12/11/17 End Time0430					
Cleanup Completed: Date N/A Time					
Probable Cause of Spill windblown trash clogged screen at diversion intake.					
Notification of CAL OES Date12/11/17 Time _1400 hours					
CAL OES Control Number 17- 8800 Tim Tribble					
Description of Spill Flow DestinationTijuana River Channel					
Spill Flow Cause windblown trash clogged screen at diversion intake.					
Spill Flow Failure Point CILA Pump Station					
Spill Flow Storm EventN/A					
Spill Corrective ActionsNone					
Spill Flow Response ActionsNone					
Spill Flow Completion Date 12/11/17 12 12 12 12 12 12 12 12 12 12 12 12 12					
InvestigationN/A Reasons Completion Date					
Health Warnings Posted Yesx_No					
Name of Beaches Impacted:NoneSurface Water Impacted:Tijuana River					
Location and No. Of Samples Collected (Type A)N/ANumber					
Parameters Tested N/A					
Regulatory Agencies Receiving ResultsN/A					
Methodology for Spill Volume EstimateCalculated from 15 min gage data USIBWC gage					
Amount of Spill Recovered None					
I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.					
Certifying Official _Steven SmullenTitle Area Operations Manager Date12/11/17					
Signature Sturi Smiller					

Spill December 1	1, 2017	Tijuana River		
Date	Time	Gage Height (m)	Flow (CMS)	Flow (MG)
12/11/2017	4:30	11.966	0.1	0.02378
12/11/2017	4:15	11.973	0.19	0.04517
12/11/2017	4:00	11.973	0.19	0.04517
12/11/2017	3:45	11.969	0.14	0.03329
12/11/2017	3:30	11.969	0.14	0.03329
12/11/2017	3:15	11.966	0.1	0.02378
12/11/2017	3:00	11.962	0.04	0.00951
12/11/2017	2:45	11.962	0.04	0.00951
	Total			0.22349 MG